


File Edit View Tools Add Help

0 Q Q

14 2 1985

Fanno Creek Trail

1985



#### 🛠 Ø⁺ & 🐼 💇 1 8 88 💊

2023

Fanno Creek

Fanna Olcek Trail

7/2004

# 2004

Site vegetation was dominated by reed canary grass and Himalayan blackberry for decades. This vegetation, and the incised stream, remained static during this time.

Image © 2024 Metro, Portland Oregonanno Creek Trail

34%


INTE

lat 45.444441° lon -122.786752° elev 167 ft eye alt 881 ft

🛶 45°F ^ ලි 🔌 🖸 🧖 ላን) 5:49 AM 2/21/2024

Google Earth

anno Creek



<u>File Edit View Tools Add H</u>elp

### – 0 ×

Fanno Crei

Cleat

### T 💱 🖉 🍼 🥶 🐼 🌌 🔍 📘 🖂 🖺 🖬 👟

6/2007

A ×

2023

Fanno Creek

.

Fanno Cleek Trail

#### progress, or ex: 15213

▼ Search

Get Directions History

Search

×


Fanno Creek Trail

2 1985

0 Q Q

I¶ ⊂ 1985






Clean Water Services implemented a massive excavation and grading project to reconnect the floodplain and re-meander Fanno Creek.

Image © 2024 Maxar Technologies Fanno Creek Trai

39%



# Primary Database Announcements Paces Places Photos Roads

Google Earth

Imagery Date: 9/6/2006 lat 45.443919° lon -122.786513° elev 169 ft eye alt 881 ft 🔾

45°F ∧ Q ≥ (€ ↓) 5:33 AM 2/21/2024

#### <u>File Edit View Tools Add H</u>elp


0 Q Q

I¶ ⊂ 1985

Fanno Creek Trail

1985

20



Borders and Labels

P Type here to search

✓ ☑ Places

Photos
 Roads

### | 🛠 🖉 ST 🥪 🗃 🕢 🚢 🔍 📗 🖂 🖺 🚳 🚳

7/2008

A X

2023

Fanno Creek

.

Fanna Oteek Trail

# YR 2 – 2008

This effort largely failed to achieve the desired result. The stream remained confined to the new channel. Planted vegetation, however, was beginning to develop, and the first beaver dam appeared in this reach (arrow)

Image @ 2024 Metro, Portland OregoFanno Creek

Imagery Date: 6/18/2008 lat 45.443915° lon -122.786523° elev 169 ft eye alt 881 ft 🔿

39%

Int

🛶 45°F ^ ලි 🔌 🗈 🧖 ላን) 5:33 AM 2/21/2024

Google Earth

Fanno

<u>File Edit View Tools Add Help</u>

### ▼ Search progress, or Search ex: 15213 Get Directions History

Progress




Fanno Creek

Fanne Greek Tral

# YR 3 – 2009


The following slides show the progression of actual substantial restoration – accomplished solely by beaver, primarily via the construction and maintenance of this singular channel-spanning dam and subsequent upstream channelspanning and encircling dams.

Image © 2024 Metro, Portland OregoFanno Creek Trail



×

Fanno Creek Trail



Google Earth

속 45°F ^ ලි 🔌 🗈 🧖 ላን) 5:34 AM 2/21/2024

anno C

X

#### Imagery Date: 6/22/2009 | lat 45.443578° |on -122.787178° | elev 159 ft eye alt 881 ft 🔘

38%

#### File Edit View Tools Add Help

#### × D.


Fanno Creek


SELO CROT


Google Earth


5:35 AM

2/21/2024












-				
9	Googl	e Ea	rth	Pro




100				
9	Googl	e Ea	rth	Pro





100			
~	Google	Earth	Pro



▼ Search

progress, or

D 0 0

▼ Places 7 🕹

V 🕹

1

V 🥖


▼ Layers


✓ / House


✓ ☑ Places

▶ 🗸 🗉 Photos ✓ P Roads


Patio








100			
0	Google	E Earth	Pro



#### File Edit View Tools Add Help






#### <u>File Edit View Tools Add Help</u>

4) Q Q

1985

Fanno Creek Trail

1985



 $\rho$  Type here to search

### ★ 0<sup>+</sup> S<sup>+</sup> S<sup>+</sup> S<sup>+</sup> (1) [2] ▲

2023

Fanno Creek

7/2023

# YR 17 – 2023

Seventeen years after project was initiated, beaver have largely rendered the human-constructed elements of the project irrelevant. Only the planted vegetation and the subsequent activities of beaver have proven effective agents of wetland restoration, now for over 15 years.

nage © 2024

Imagery Date: 7/1/2023 lat 45.443922° lon -122.786512° elev 169 ft eye alt 881 ft 🔘

34%

속 45°F ^ ලි 🔌 🗈 🧖 ላን) 5:48 AM 2/21/2024

Google Eart

▼ Search

progress, or

D 0 0

▼ Places

Layers

💌 🗏 🮯 Primary Database

✓ ☑ Places

Photos
 Photos
 Roads

Announcements

Borders and Labels

🕈 🗌 📚 My Places

ButlerCredits

Sightseeing Tour Make sure 3D Buildings layer is checked Start tour here

#### <u>File Edit View Tools Add H</u>elp

Progress

Search

-**B**H

1985

Get Directions History


## 🔽 🛠 🖉 🕸 🐼 🌌 🖉 🖺 🖾 🔍

.

7/2003

# 2003

This adjacent portion of the Fanno Creek floodplain was not manipulated with excavation and construction. The site was similarly dominated by reed canary grass and blackberry.



Google Earth

Imagery Date: 7/17/2003 lat 45.445746° lon -122.787984° elev 159 ft eye alt 487 ft 🔵

65°F ^ @ 📉 🖅 🌈 🕼

80%

### ▼ Search 1.1 Search progress, or Get Directions History Progress D 0 0 × ▼ Places 🕈 🗌 📚 My Places ButlerCredits Bightseeing Tour Make sure 3D Buildings layer is checked Start tour here F. 66 1 T 71 - Ext Layers 💌 🗏 🮯 Primary Database Announcements Borders and Labels ✓ ☑ Places Photos Roads 1985 1 片

## i 😯 🖉 🌫 🚭 💽 🚢 🔍 📋 🖂 🖺 📧 💿

6/2006

# 2006 – Yr 1

The area was mowed and planted with willow, cottonwood, ash and other woody vegetation.

Image © 2024 Metro, Portland Oregon

Google Earth

P,

12:11 PM


3/16/2024

Imagery Date: 6/22/2006 lat 45.445746° lon -122.787984° elev 159 ft eye alt 487 ft 🔘


80%


🛛 🚺 Rec... \land 😳 📉 🖅 🌈 🕼

P,




#### <u>\</u> **E** 0 1 ▼ Search 2 X 2009 – Yr 4 Search progress, or 7/2009 **Get Directions History** Woody vegetation begins to fill in the site. Progress D 0 0 × ▼ Places My Places ButlerCredits layer is checked Start tour here F. 66 1 T **T1** 100 \* + Layers 💌 🗏 🮯 Primary Database Announcements Image © 2024 Metro, Portland Oregon Borders and Labels ✓ ☑ Places Google Earth Photos ✓ ₽ Roads Imagery Date: 6/22/2009 lat 45.446067° lon -122.788043° elev 161 ft eye alt 487 ft 🔘 1985 12:11 PM 3/16/2024 🛛 🚺 Rec... 🔨 😳 📉 🖅 🌈 🕼 片 Int 80%







-					
-	Googl	e Fa	arth	Pro	
densed.	ooogi	~ ~		110	




Goo Goo	ale	Earth	Pro



100				
9	Googl	e Ea	rth P	ro






File Edit View Tools Add Help









File Edit View Tools Add Help


0 Q Q

14 0

1985

1985

2



#### 🛠 🖉 🍪 🥔 🚭 E 🖹 📧 👟 2

7/2012

A X

2023

-

# YR 2 – 2012

The ponded area in upper right corner fills as a result of beaver activity downstream of the project. Hydrology on the remainder of the site was largely unaffected by mass excavation, channel relocation and structures.

Roderick Creek

lat 45.549567° lon -123.186136° elev 218 ft eye alt 1260 ft 🔘 Imagery Date: 7/6/2012


30%

Int

🜊 45°F \land ਉ 🔌 🖬 🧖 ላን)

Google Earth

6:01 AM 2/21/2024




Google Earth

eye alt 1260 ft

6:01 AM

2/21/2024



1.1

4 Q Q

I¶ ⊂ 1985

1985

2

The state of the state

### ) 🛠 🖉 & 🚭 💽 🚢 🔍 📳 🖂 🖺 🚳 🚳

6/2017

2023

X

# YR 7 – 2017

Beaver dam maintenance and enhancement continues at the first location and begins at many additional sites upstream. Downstream dams continue to be removed however, and fish and eggmass kills continue on lower ponds.

Roderick Creek

Google Earth

6:01 AM

2/21/2024


Imagery Date: 6/22/2017 lat

Int

30%

lat 45.549560° lon -123.186145° elev 218 ft eye alt 1260 ft 🔘

🜊 45°F \land ਉ 📉 🗗 🌈 ላ୬)



Progress


Search


progress, or

Get Directions History

Search

#### 🔲 🛠 🖉 🔤 🚳 🜌 🔍 📗 🖂 🖻 📧 🤇





## YR 13 – 2023

Finally, in 2023, the Glenwood consultant (landowner) induced beaver to build and maintain a dam upstream of bridge within bounds of the protected easement.


Grading and construction failed to achieve wetland restoration at Half Mile. **Only** the restoration of willows and other beaver-supporting vegetation have generated any substantial wetland restoration, and beaver have persisted in sustaining these gains now for a decade. Wetlands continue to expand both within and outside the project boundary. 21 Nov 2020 This dam was constructed Fall 2020 on Roderick Creek below Half Mile Wetland 26 Dec 2020 Same dam the following month.

a substitute of

**08 Jan 2021** The day the dam was excavated by neighboring farmer.

Nelsad

15 Jan 2021 Seven days later, beaver have made substantial progress on re-build. **17 Jan 2021** Nine days later, major reconstruction complete. **O8 May 2021** Dam was removed again in April 2021, but largely rebuilt by May 2021. Dams have been removed and rebuilt in this location at least forty times in the past ten years, each removal resulting in turbidity flushes and losses of fish and amphibians.





2 1985

Imagery Date: 6/27/1994 lat 45.613821° lon -123.

and dams continuously removed.



terest and other features

7/2000

# Cedar Canyon Creek Image U.S. Geological Survey

### 2000

Banks Wetland, four years after cessation of beaver control.

Ν

~ (0)

**()** 

-

lat 45.613390° lon -123.1 Imagery Date: 7/29/2000

1985



# 2004

Eight years after cessation of beaver control. No other treatments applied.

